

5599C

~~6291277~~

REPRINT	62920403	Sur. ZAR	TAX INVOICE	917466895
TAX INVOICE	PAGE 1 OF 1			28.02.2024
VAT REG NO.	NA		TELEPHONE	+27(0)1021

DELIVERY NO.	40622098	FAX	+27(0)1021
SHIPMENT NO.	2258495	CUSTOMER NO.	45477
DELIVERY MODE	Primary Delivery	TAX CLASS	
DELIVERY DAY	Inter-Co/Plant/Direc	CUST. REF.	TRUCK 7

SALES ORDER NO.	19696496
--------------------	----------

Gross Weight: 34169 Kg	
Bottle Deposit Total: 45017.28	
TOTAL:	590612.00

881024

CHEP**Exchange Out**

A Brambles Company

5000013729949

From	References	Dates
CHEP Global ID 1000125761 Address: Heineken Group Exchange Account cnr Bernie and Harm Street CAPE TOWN, 8000 SOUTH AFRICA Tel: +27218097642 Fax:	Reference 40622098 Other Reference 45477	Shipment Date 28/02/2024 Capture Date 28/02/2024

Transporter OWN TRANSPORT

Vehicle Reg No JBD353FS

Shipped To	* Notes (Hand Written):
CHEP Global ID 1000133368 Address: 45477-Mthunzini's Liquor Store Stand 1701 Block P SOSHANGUVE, 0152 SOUTH AFRICA Tel: Fax:	28 Pallets loaded Created By PP-BALOYIG

Equipment	Shipped	Returned / Redeemed	Outstanding	Partner Balance
1-B1210A-1200x1000 Block Pallet	28	0	28	138-
Total	28	0	28	138-

P.N. Louw
02-03-24

Shipper's Signature 	Received By SAMAH	Driver Name THABANG
Date Received 28/02/24	Receiver's Signature and Date 28/02/24	Driver's Signature

LR SEDIBENG SEAL REGISTER



Liquor Runners

Vehicle Registration	Trailer 1	Trailer 2	Order nr
JBD3535	FIMM6295	HMM02205	

No of Seals
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16

Received by Driver

Seal Number
00017 47001
00017 47002
00017 47003
00017 47004
00017 47005
00017 47006
00017 47007
00017 47008
00017 47009
00017 47010
00017 47011
00017 47012
00017 47013
00017 47014
00017 47015
00017 47016

Date: 28/02/24

Time:

28 pallets

Total pallets loaded:

Depot quality check on dented/leaking stock (damage)	
Transporter quality check on dented/leaking stock (damage)	

DRIVER NAME

Thabang

CONTROLLER NAME

Jeffrey

CHECKER NAME AND SURNAME

DRIVER SIGNATURE

CONTROLLER SIGNATURE

CHECKER SIGNATURE

LR SEDIBENG SEAL REGISTER



Liquor Runners

Vehicle Registration	Trailer 1	Trailer 2	Order nr

No of Seals
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16

Received by Driver

Seal Number
00017 47001
00017 47002
00017 47003
00017 47004
00017 47005
00017 47006
00017 47007
00017 47008
00017 47009
00017 47010
00017 47011
00017 47012
00017 47013
00017 47014
00017 47015
00017 47016

Date: 28/02/24

Time:

28 pallets

Total pallets loaded:

Depot quality check on dented/leaking stock (damage)	
Transporter quality check on dented/leaking stock (damage)	

DRIVER NAME

TH Gbang

CONTROLLER NAME

Jeffrey

CHECKER NAME AND SURNAME

DRIVER SIGNATURE

CONTROLLER SIGNATURE

CHECKER SIGNATURE



LIQUOR RUNNERS TT & TRA PRE & POST-TRIP INSPECTION

FL 12

Rev 01

LDV Registration Number

J8D 353FS T.HMM 019FS

Trip Sheet

T.HMM 022

KM Reading:

450202FS

Date

28/02/23

Time

23:00

Bold and Highlighted items are SAFETY CRITICAL ITEMS. If any of these points are found to be defective the equipment must not be despatched unless repaired, noted and signed off by a suitable qualified person on the PRE TRIP and job card attached of such a repair. In case of an incorrect identification of defect especially critical points a suitable qualified person should note and sign off an agreement on the PRE-TRIP sheet.

YES

If in order

NO

If in need of attention - give brief detail below

#	Importance	Category	Pre Trip Description	PRE TRIP	POST TRIP
1	Major	Engine	Are the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
2	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
3	Major	Engine	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
4	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
5	Major	Engine	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
6	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
7	Major	Engine	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
8	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
9	Major	Engine	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
10	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
11	Major	Engine	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
12	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
13	Major	Engine	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
14	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
15	Major	Engine	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
16	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
17	Major	Engine	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
18	Major	Engine	Is the engine fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
19	Major	Body /Truck & Trailer	Are the truck and trailers clean and free from accident damage? If NO, please indicate damage region on reverse with a brief description.	yes	yes
20	Major	Number & Fleet Plates	Are all fleet number plates and registration number plates intact and clearly visible on truck and trailers?	yes	yes
21	Major	Air Build Up	Is the time for air pressure build up less than 10 minutes?	yes	yes
22	Minor	Air tank	Is there any moisture remaining in the air tanks? Please drain if needed.	yes	yes
23	Major	Visible Leaks	Are there any visible leaks under the vehicle? i.e. oil, water, diesel or grease	yes	yes
24	Major	Fluid Level Checks	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	yes	yes
25	Major	Fuel Check	Is the vehicle fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	yes	yes
26	Major	Clutch Play	Is the clutch free of excess play and operating correctly? (not slipping)	yes	yes
27	Major	Occupants	Is the number of persons inside the cab matching the number as indicated on the license disc including the driver?	yes	yes
28	Minor	Housekeeping Truck	Is the interior of the cab clean, free from loose objects, food, pests, foreign chemicals, oil & diesel not stored inside the cab?	yes	yes
29	Minor	Triangles	Are there emergency triangles available for each set of number plates per vehicle combination? 3 sets per 6 x 4 TT & interlink trailer	yes	yes
30	Minor	Appearance	Is the truck, trailer & tarpaulins clean, neat and presentable?	yes	yes
31	Minor	Tarpaulin	Are the tarpaulin ratchets, buckles & straps operating correctly? Are the tarpaulins and decals presentable and free from tears?	yes	yes
32	Minor	Panic Button	Do you know where the location of the panic button is?	yes	yes

Driver Comments:

Supervisor/Manager Resolution of Safety Critical Items Flagged:

Sedibeng Brewery
Kliprivier Business Park
1 De Man Road, Midvaal
Johannesburg



Sedibeng Brewery
Kliprivier Business Park
1 De Man Road, Midvaal
Johannesburg

Lodewyk.dewet@lrsa.co.za

Liquor Runners Sedibeng SEDIBENG PRIMARY

010 010 0551

www.lrsa.co.za

GRV for RETURNABLES - LRSA NR: 10192 (GRV)

Receiver: Asande Maqhubu

Checker: Nthabiseng Mofokeng

Warehouse: MTHUNZINI LIQUOR STORE

Sender Ref 1: 86461297

Receive Date: 2024-03-02

Warehouse Recv: SEDIBENG

Sender Ref 2: 62951292

SKU Code	Stock Description	Bin	Batch Number	QTY(Cases)	QTY(Units)
Single Units					
4085904	Pallet Rental Wood Chep			0	7
				0.00	7.00

Full Cases					
4085945	Crate Own Generic 12 x 660ML	108		539	0
4085918	RB Empty Generic			6468	0
				7,007.00	0.00

Single Units					
4023385	Pal Distell 4-Way (1000x1200)			0	1
				0.00	1.00

Full Cases					
4058358	Crate 12x660ml			66	0
4018870	Distell RB 660ml			792	0
				858.00	0.00
Total QTY Received				7,865.00	8.00

Checked By: Nthabiseng

Transport Company: Liquor Runner

02/03/2024 12:16:04 PM

Receiver: JBD 353 FS

Checker: PATRICK

Driver Signature: