


Outgoing

DELIVERY NOTE

Page 1 OF 1



Heineken Beverages (SA) (Pty) Ltd

Reg.No. 2003/026165/07

Vat No. 4180211080

NLA Reg. No: RG0003175

62928114

Supplying Plant Sedibeng Brewery 1DE MAN STR, KLIPPRIVIER IND AREA KLIPPRIVIER 1871 SOUTH AFRICA	Delivery Number	40626468
	Despatch Date	26.02.2024
	Shipment Number	2260185
	Purchase Order Number	4401702071
	Shipping Condition	Inter-Co/Plant/Direc
	Transporter	Liquor Runner George (Pty) Ltd
	Ship To Distell - Pretoria West (Dist) Distell - Pretoria West (Dist) 317 Van der Hoff Road PRETORIA 0030 SOUTH AFRICA	Vehicle Registration
Trailers Registration		/
Seal nr		HZP765FS / /
Delivery Instructions:		

Item	Material	Material Description	Batch	Order Qty & Unit	Gross Weight
000010	0070406	SOL NRB Case 4(6x330ml) Ba ZA		0.000 CS	0.000
000020	4085904	Pallet Rental Wood 1200x1000mm CHEP		28.000 PC	560.000
900010	0070406	SOL NRB Case 4(6x330ml) Ba ZA	A4031710A1	2.352.000 CS	31.554.432
Total weight:					32.114.432

761490		26/02/24
DRIVER NAME	DRIVER SIGNATURE	DATE
Dennis		26/02/24
SECURITY NAME	SECURITY SIGNATURE	DATE
Japuta		26/02/24
RECEIVER NAME	RECEIVER SIGNATURE	DATE
SECURITY NAME	SECURITY SIGNATURE	DATE



Transfer OUT



4242434577

A Brambles Company

From: CHEP Global ID: 101032817 Address : ZAB1 - Heineken Beverages Prim 1 De Man Street Klipriver Business Inanda Greens Business Park KLIPRIVER 1960 SOUTH AFRICA Tel: +270102161000 Fax: +270102161022 (0)00 000 0000	References: Reference: 4401702071 Other Reference: 40626468	Dates : Shipment Date: 25/02/2024 Effective Date: 25/02/2024 Capture Date: 25/02/2024
---	--	--

Transporter: Own Transport		Vehicle Reg No: HZP765FS
Shipped To: CHEP Global ID: 101083093 Address: Heineken Beverages Pretoria We 1317 Van der Hoff Road, Kirkney Ext Inanda Greens Business Park ZANDFONTEIN 0884 SOUTH AFRICA Tel: +270123729100 Fax: +270867658077	Notes(Hand Written):	
	Created by: Djantji Voyokazi :- pp-djantjvo patricia@lrsa.co.za	

Equipment	Quantity
1-B1210A-1200x1000 Block Pallet	28
Total	28

Shipper's Signature Vuyokazi	Received By Japhet	Driver Name MANDLA
Date Received	Receiver's Signature and Date 26/02/24	Driver's Signature

LR SEDIBENG SEAL REGISTER



Liquor Runners

Vehicle Registration	Trailer 1	Trailer 2	Order nr
H2P 765 FS	H2R 949 FS	H2R 951 FS	62928110

No of Seals
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16

Received by Driver

Seal Number
00017 52273
00017 52274
00017 52275
00017 52276
00017 52277
00017 52278
00017 52279
00017 52280
00017 52281
00017 52282
00017 52283
00017 52284
00017 52285
00017 52286
00017 52287
00017 52288

Date: 26/02/20

Time: 00:14

Exit Weight: 52240

Total pallets loaded: 28

Depot quality check on dented/leaking stock (damage)	
Transporter quality check on dented/leaking stock (damage)	

DRIVER NAME

Mandla

SECURITY NAME

LR NAME AND SURNAME

INDUMU

DRIVER SIGNATURE

SECURITY SIGNATURE

LR SIGNATURE

H2R949 FS / H40K95107

LIQUOR RUNNERS TT & TRA PRE & POST-TRIP INSPECTION

FL 12

OV Registration Number

H2P765 FS

Rev 01

Trip Sheet

KM Reading: 573523829K

Date 27-02-20

Time 08:00

Bold and Highlighted items are SAFETY CRITICAL ITEMS. If any of these points are found to be defective the equipment must not be despatched unless repaired, noted and signed off by a suitable qualified person on the PRE TRIP and job card attached of such a repair. In case of an incorrect identification of defect especially critical points a suitably qualified person should note and sign off on agreement on the PRE-TRIP sheet.

YES If in order NO If in need of attention - give brief detail below

#	Importance	Category	Pre Trip Description	PRE TRIP	POST TRIP
1	Critical	Lights	Lights - Are all headlights, park lights, reverse signal & buzzer, indicators, and horns operating correctly, with lenses intact and no cracks?		
2	Critical	Mirror	Mirror - Are all mirrors intact and providing the necessary view?	Yes	
3	Critical	Hooter	Hooter - Is the hooter audible and operating correctly?	Yes	
4	Critical	Braking System	Is the hand brake and foot brake functioning correctly without any audible air leak?	Yes	
5	Critical	Braking System	Is the exhaust brake retarder and engine stop operating correctly?	Yes	
6	Critical	Warning Signals	Are there any warning symbols illuminated on the instrument cluster?	Yes	
7	Critical	Oil Pressure	Is the oil pressure not less than 1 bar when idling, and 3 bar at full rev with engine at operating temperature?	Yes	
8	Critical	Gauges / ODO Meter	Are all the gauges and ODO meter of the instrumentation cluster operating and displaying information correctly?	Yes	
9	Critical	Trailer Hitched to the Fifth Wheel	Are the truck and trailers properly hitched, lock block and safety hook in place, with fifth wheels properly lubricated?	Yes	
10	Critical	Vehicle License Truck	Is the operators card, and license disc current, valid and clearly visible/legible, secured at the bottom left corner of the windscreen? (All old discs removed)	Yes	
11	Critical	Vehicle License Trailers	Is the operators card, and license disc current, valid and clearly visible/legible, secured on the left side of chassis beam with license disc holder. Leader & Follower trailers	Yes	
12	Critical	Front Wheels / Steer	Are the tyres on the steering axle new or recap casings and matching? i.e. size, brand, tread pattern (at least 3mm tread), free of cuts, uneven wear etc.	Yes	
13	Critical	Rear Wheels	Are the tyres new or recap casings matching? i.e. size, brand, tread pattern (at least 3mm tread), free of cuts, uneven wear etc.	Yes	
14	Critical	Trailer Wheels	Are the tyres new or recap casings matching? i.e. size, brand, tread pattern (at least 3mm tread), free of cuts, uneven wear etc.	Yes	
15	Critical	All Wheels	Are the steel valve caps and inner valve extensions fitted and wheels cleaned?	Yes	
16	Critical	All Wheels	Are all wheel nuts and studs in place and tight and are there at least 4 torque indicators fitted and this free of visible buckling? (No missing and broken wheel studs and nuts)	Yes	
17	Critical	Windscreen	Is the windscreen clean and free of cracks?	Yes	
18	Critical	Wipers	Are the window wipers in proper working order and not worn or torn?	Yes	
19	Major	Body / Truck & Trailer	Are the truck and trailers clean and free from accident damage? If NO, please indicate damage region on reverse with a brief description.	Yes	
20	Major	Number & Fleet Plates	Are all fleet number plates and registration number plates intact and clearly visible on truck and trailers?	Yes	
21	Major	Air Build Up	Is the time for air pressure build up less than 10 minutes?	Yes	
22	Minor	Air tank	Is there any moisture remaining in the air tanks? Please drain if needed.	Yes	
23	Major	Visible Leaks	Are there any visible leaks under the vehicle? i.e. oil, water, diesel or grease	Yes	
24	Major	Fluid Level Checks	Has the engine oil level, coolant level, power steering fluid and brake fluid been checked and found sufficient?	Yes	
25	Major	Fuel Check	Is the vehicle fueled sufficiently for the trip? (visual inspection of fuel level done by removing diesel tank cap, as fuel gauge might be faulty).	Yes	
26	Major	Clutch Play	Is the clutch free of excess play and operating correctly? (not slipping)	Yes	
27	Major	Occupants	Is the number of persons inside the cab matching the number as indicated on the license disc including the driver?	Yes	
28	Minor	Housekeeping Truck	Is the interior of the cab clean, free from loose objects, food, pests, foreign chemicals, oil & diesel not stored inside the cab?	Yes	
29	Minor	Triangles	Are there emergency triangles available for each set of number plates per vehicle combination? 3 sets per 6 x 4 TT & interlink trailer	Yes	
30	Minor	Appearance	Is the truck, trailer & tarpaulins clean, neat and presentable?	Yes	
31	Minor	Tarpaulin	Are the tarpaulin ratchets, buckles & straps operating correctly? Are the tarpaulins and decals presentable and free from tears?	Yes	
32	Minor	Panic Button	Do you know where the location of the panic button is?	Yes	

Driver Comments:

12 meter trailer dont on a dumper and light

Supervisor/Manager Resolution of Safety Critical Items Flagged:

Controller Name:

Drivers Name:

Controller Signature:

Drivers Signature: